

Turbo HD DVR V3.4.88 build 180207 Release Notes (2018-02-10)

	Firmware Version:	V3.4.88 build 180207
	SDK Version:	V5.3.1.45 build20171011
Firmware	Play Library (PlayCtrl.dll)	6.0.0.5
Basic Information	player	7.3.3.64
	Web version	V4.0.1 build 171130
	Client version	V2.6.5.17Build20171214

Reason of Upgrade

Update some system service, newly support combination of letters and numbers as serial number. This version is only suitable for DS-71/7200HGHI-Fx/N, DS-71/7200HGHI-Fx, DS-71/72/73/8100HQHI-Fx/N, DS-72/73/76/81/9000HUHI-Fx/N. adds some new functions, modify some functions, enhance products quality and meet customers' requirements.

Main update

Modified function

- i. Fix the issue that the serial numbers of some IPCs display abnormally on IPC list.
- ii. Fix the issue that the heat map information of IP channel displays abnormally on DS-73/81/9000HUHI-Fx/N series DVR.
- iii. Optimize the search function on device web.
- iv. Note:
 - Firmware version V3.4.88 Build180131 is suitable for
 DS-71/7200HGHI-Fx/N,DS-71/7200HGHI-Fx,DS-71/72/73/8100HQHI-Fx/N and
 DS-72/7600HUHI-Fx/N
 - 2. Firmware version V3.4.88 Build 180207 is suitable for DS-73/81/9000HUHI-Fx/N
- **v.** Other issue fixed.



Related product list:

	DS-7104HGHI-F1/N、DS-7108HGHI-F1/N、DS-7116HGHI-F1/N	
	DS-7204HGHI-F1/N、DS-7208HGHI-F1/N、DS-7216HGHI-F1/N	
	DS-7104HQHI-F1/N、DS-7108HQHI-F1/N、DS-7116HQHI-F1/N	
	DS-7204HQHI-F1/N、DS-7208HQHI-F1/N、DS-7208HQHI-F2/N	
	DS-7216HQHI-F1/N、DS-7216HQHI-F2/N	
	DS-7304HQHI-F4/N、DS-7308HQHI-F4/N、DS-7316HQHI-F4/N	
	DS-8104HQHI-F8/N、DS-8108HQHI-F8/N、DS-8116HQHI-F8/N	
5/5/5 : 7	DS-7104HGHI-F1、DS-7108HGHI-F1、DS-7116HGHI-F1	
-F/N Series Turbo	DS-7204HGHI-F1、DS-7208HGHI-F1、DS-7208HGHI-F2	
HD DVR	DS-7216HGHI-F1、DS-7216HGHI-F2	
	DS-7204HUHI-F1/N、DS-7208HUHI-F1/N	
	DS-7204HUHI-F2/N、DS-7208HUHI-F2/N、DS-7216HUHI-F2/N	
	DS-7604HUHI-F1/N、DS-7608HUHI-F2/N、DS-7216HUHI-F2/N	
	DS-7304HUHI-F4/N、DS-7308HUHI-F4/N、DS-7316HUHI-F4/N	
	DS-8104HUHI-F8/N、DS-8108HUHI-F8/N、DS-8116HUHI-F8/N	
	DS-9004HUHI-F8/N、DS-9008HUHI-F8/N、DS-9016HUHI-F8/N	
	DS-9008HUHI-F16/N、DS-9016HUHI-F16/N	

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support team.

Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.

Tel: +86-571-8807-5998 FAX: +86-571-8993-5635 Email: support@hikvision.com