

# Network Camera Firmware Version: V5.4.6 Release Note (External) (2018-03-14)

	Firmware Version:	V5.4.6 build 180119
	SDK Version:	V5.2.7.45_build20170612
	Play Library (PlayCtrl.dll)	V7.3.3.61
Firmware	Encapsulation Library	V2.5.2.5
	(SystemTransform.dll)	
Basic Information	Voice intercom library	V1.4.0.3
	(AudioIntercom.dll)	
	iVMS-4200	V2.5.13.2 build170709
	IE Client version	V4.0.1 build170711
		V3.0.6.26

## **Hikvision Firmware V5.4.6 Features**

### \*for 1X01-(B) Network Cameras (V5.4.6)

#### **New Features**

• <u>SN (Series number) is the combination of numbers and letters.</u>

#### **Improved Features**

- For OSD Text Overlay, the character which in the font library GBK but out of the font library GB2312 will be displayed as "□".
- <u>Hik-Connect APP supports zoom in/out for motorized lens camera.</u>
- The audio linkage of PIR and motion detection can be disabled on the Hik-Connect APP.
- <u>Remove the support to Genetec.</u>

#### **Compatibility Update**

• HIKCGI version: V2.0;

External



- ISAPI version: V2.4;
- ONVIF version: V1612, official test tool version: V1701;
- <u>Milestone:</u>
  - 1. Milestone Enterprise 8.1a(10.2a), Milestone drive version (Driver 9.1), test HIKCGI
  - 2. Milestone software version (Milestone Corporate 11.1a), Milestone drive version (Driver 9.1), test HIKCGI

#### • Avigilon:

- 1. Control Center: V5.10.12.2;
- 2. Test ONVIF.

#### • Excaqvision:

- 1. Version: 8.4.2
- 2. Protocol: HIKCGI, ONVIF

#### • Tested NVRs:

DS-96256NI-I24/H (baseline V3.2.8\_170213\_05)

96000 I Series

96000NI-I Series NVR (V3.6.21) DS-96256NI-I24 or DS-96256NI-I24/H

E Series: DS-7732NI -E4/16P (V3.4.92)

Netra DVR: DS-9016HFI-ST (V3.4.3)

Note: The compatibility of IPC and NVR models in the same NVR series is the same.

#### • <u>Tested Keyboard:</u>

DS-1600KI V2.0.0

DS-1006KI V1.0



## **Customer Impact and Recommended Action**

This update refers to function/compatibility improvement and will take effect automatically after the

Date of Change. We are very sorry for any inconvenience of use-habit changes caused by this action. For any questions and request for this firmware, please contact our local technical support team.

#### Remarks:

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice.
- Product design and specifications are subject to change without prior notice.
- The Hikvision firmware may contain defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.
- Hikvision is not liable for any typing or printing errors.

Hikvision Digital Technology CO., Ltd. No. 555 Qianmo Road, Binjiang District, Hangzhou 310051, China Tel: +86-571-8807-5998 FAX: +86-571-8993-5635 Email: overseabusiness@hikvision.com

## **Supported Product List**

Product Category	Model Number	Product Description
Mini IR Bullet	DS-2CD1201(D)-I3/I5(B)	1MP, IR
IR Turret	DS-2CD1301(D)-I(B)	1MP, IR