

# Network Camera Firmware Version: V5.5.5 Release Note (External) (2018-04-09)

Firmware	Firmware Version:	V5.5.5 build180409
	SDK Version:	V5.2.7.45 build170612
	Play Library (PlayCtrl.dll)	V 2.5.11.1 build170526
	Encapsulation Library	V2.5.2.5
	(SystemTransform.dll)	
Basic Information	Voice intercom library	V1.4.0.3
	(AudioIntercom.dll)	
	iVMS-4200	V2.5.13.2 build170709
	IE Client version	V4.0.1 build170711
		V3.0.6.26

## Hikvision Firmware V5.5.5 build180409 Features

- 1. New Features
  - New model samples of 1 series are released,

#### 2MP: DS-2CD1621G0-I(Z), DS-2CD1721FWD-I(Z)(B)

#### 3MP: DS-2CD1631G0-I(Z), DS-2CD1731FWD-I(Z)(B)

Support SD card storage, motorized variable focal lens, and four languages: English, Russian,

Spanish, Portuguese.

• Optimize the performance of auto focus and fix the defocus issue during zoom in/out process.

#### **Compatibility Update**

- HIKCGI version: V2.0;
- ISAPI version: V2.4;
- ONVIF version: V1612, official test tool version: V1701;



### • <u>Milestone:</u>

- 1. Milestone Enterprise 8.1a(10.2a), Milestone drive version (Driver 9.1), test HIKCGI
- 2. Milestone software version (Milestone Corporate 11.1a), Milestone drive version (Driver 9.1), test HIKCGI
- <u>Avigilon:</u>
  - 1. Control Center: V5.10.12.2;
  - 2. Test ONVIF.
- Excaqvision:
  - 1. Version: 8.4.2
  - 2. Protocol: HIKCGI, ONVIF
- NAS(Only test for Brainaire):

DS-A2016R, DS-A1016RS V2.2.0-7

### • <u>Tested NVRs:</u>

DS-96256NI-I24/H(baseline V3.2.8\_170213\_05)

96000 I Series

96000NI-I Series NVR (V3.6.21)

E Series: DS-7732NI -E4/16P(V3.4.92)

G Series: DS-7608NI-G2/4P(V3.4.1 build 151225)

K Series: V3.4.93

Netra DVR: DS-9016HFI-ST(V3.4.3)

Note: The compatibility of IPC and NVR models in the same NVR series is the same.



## **Customer Impact and Recommended Action**

This update refers to function/compatibility improvement and will take effect automatically after the

Date of Change. We are very sorry for any inconvenience of use-habit changes caused by this action. For any questions and request for this firmware, please contact our local technical support team.

#### <u>Remarks:</u>

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice.
- Product design and specifications are subject to change without prior notice.
- The Hikvision firmware may contain defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.
- Hikvision is not liable for any typing or printing errors.

Hikvision Digital Technology CO., Ltd. No. 555 Qianmo Road, Binjiang District, Hangzhou 310051, China Tel:+86-571-8807-5998 FAX:+86-571-8993-5635 Email: overseabusiness@hikvision.com